



**PERFORMA REGARDING SAFE DRINKING WATER AND SANITARY  
CONDITION CETFIFICATE**

**NO:** BBMP/HS/PR/41/2019-20

**DATE:** 23-08-2019

It is certified that an inspection team headed by **Dr.Kalpana.P. Deputy Health Officer** and **Devaraj M. Sr.H.I.** (Name Of Officers with designation) from **BBMP Health Department** (Name of Department /Office) Inspected the **GJR International School, Chinnappanahalli, Near AECS Layout, Marathahalli, Bangalore-37.** (Name & Address of the school) on **20-08-2019** and found that the **GJR International School** (Name of School) has safe drinking water facilities for the students and members of staff of the institution and is maintaining the hygienic sanitation condition in the school building, the campus and building in safety conditions as per the norms prescribed by the central /state/U.T.Govt.

Signature with Seal:  
Name  
Designatin

*[Handwritten Signature]*  
23/8/19  
: **Dr.Kalpana.P**  
: **Deputy Health Officer**  
BBMP Mahadevapura Zone.

**To,**  
GJR International School,  
Chinnappanahalli,  
Near AECS Layout,  
Marathahalli, Bangalore-37

*[Handwritten Signature]*  
Principal  
GJR International School